

## CMK2-\*C Series



## CMK2-\*C Series

How to order



## How to order mounting bracket

Bore size (mm)  Mounting bracket	ø20	ø25	ø32	ø40
Basic (00) *3	M1-00-20	M1-00-30	M1-00-30	M1-00-30
Axial foot (LB/LS)	M1-LB-20	M1-LB-30	M1-LB-30	M1-LB-30
Flange (FA/FB)	M1-FA-20	M1-FA-30	M1-FA-30	M1-FA-30
Trunnion (TA/TB)	M1-TA-20	M1-TA-30	M1-TA-30	M1-TA-40
Eye bracket (CA)	M1-CA-20	M1-CA-30	M1-CA-30	M1-CA-30
Clevis bracket (CB)	M1-CB-20	M1-CB-30	M1-CB-30	M1-CB-30

<sup>\*1:</sup> Regarding mounting brackets, mounting nuts and toothed washers are supplied with the axial foot and flange. The trunnion includes mounting nuts.

SCP\*3

CMK2

CMA2

SCM

SCG

SCA2

SCS2

CKV2

CAV2/ COVP/N2

SSD2

SSG

SSD

CAT

MDC2

MVC

SMG

MSD/ MSDG

FC\*

STK

SRL3

SRG3

SRM3

SRT3

MRL2

MRG2

SM-25

ShkAbs

FJ

FK

Spd Contr

Ending

<sup>\*2:</sup> For axial foot (two-sided), 2 sets of "M1-LB-\*" in the table above are required.

<sup>\*3:</sup> Mounting nut, toothed washer only. Although 1 set is included with the basic of the product (00), use this when needed.